

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/24/2021

Submitted Date:

12/07/2021

Document Number:

688801074

FIELD INSPECTION FORMLoc ID 324481 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		geops@oxbow.com	Inspection mail box
Fischer, Alex		alex.fischer@state.co.us	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283921	WELL	PR	06/01/2020	GW	051-06071	HOTCHKISS FEDERAL 12-89 18-31	EI
284076	PIT	AC			-	HOTCHKISS FEDERAL 18-31	EI

General Comment:

On November 24, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gunnison Energy LLC Hotchkiss Federal 12-89 #18-31. For the most recent field inspection report of this facility, please refer to document #699802733.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign mounted to stock panel fencing around well head and pump jack.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on well sign.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Stock panel enclosure.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Electric motor.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Generator		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Combo unit with separator.		
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	283921	Type:	WELL	API Number:	051-06071	Status:	PR	Insp. Status:	EI
Facility ID:	284076	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	EI

Environmental

Spill/Remediation:

Comment: Pit Facility ID #284076 has an active status in the COGIS database. No pit was observed during this inspection.

Corrective Action: Per Rule 913.c.(1) the operator will submit a Form 27 for closure of Pit Facility ID #284076.

Date: 01/07/2022

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Pit Facility ID #284076 has an active status in the COGIS database. No pit was observed during this inspection.

Corrective Action: Per Rule 909.a.(3) the operator will update this Facility status on a Form 15.

Date: 01/07/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Type: Reserve Lined: Pit ID: 284076 Lat: 39.019960 Long: -107.375150

Reference Point: Other: Length: Width:

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Comment:

Corrective Action

Date:

COGCC Comments

Comment	User	Date
On November 24, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Gunnison Energy LLC Hotchkiss Federal 12-89 #18-31. For the most recent field inspection report of this facility, please refer to document #699802733. Pit Facility ID #284076 has an active status in the COGIS database. No pit was observed during this inspection. Per Rule 909.a.(3) the operator will update this Facility status on a Form 15. Per Rule 913.c.(1) the operator will submit a Form 27 for closure of Pit Facility ID #284076.	hughesjo	12/07/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402891348	INSPECTION SUBMITTED	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599981

688801075	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599980
-----------	-------------------	---

