

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/02/2021

Submitted Date:

12/07/2021

Document Number:

689806700

FIELD INSPECTION FORMLoc ID 434014 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10598

Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Boyer, David	303-994-0000	david@d90energy.com	
Inspections, General		sandridgeenvironmental@sandridgeenergy.com	All Inspections

General Comment:

FLIR inspection in response to compliant 402880151. The complainant claimed emissions were observed from tank battery. Emissions were observed from the southeast tank in the battery during COGCC FLIR inspection. Inspector contacted D90 on 12/2/2021 and informed them of the observed emissions. D90 assured inspector that emissions would be addressed immediately. D90 expressed concern of trespassing and tampering during this conversation. Inspector recommended contacting the local sheriff and installing additional security measures on location if tampering/trespass was a safety concern.

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.593783 Long: -106.414020Wind: Light Speed: (mph) Direction From: West Weather: Clear Temperature: 56 (F)Assisting Staff Emily Waldron Camera #: 3☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
1:30	PM	1:45	PM

Equipment
Water Tank(s)
Oil Tank(s)

Comment: FLIR inspection in response to compliant 402880151. The complainant claimed emissions were observed from tank battery. Emissions were observed from the southeast tank in the battery during COGCC FLIR inspection. Inspector contacted D90 on 12/2/2021 and informed them of the observed emissions. D90 assured inspector that emissions would be addressed immediately.

Corrective Action: Immediately cease venting.

Date: 12/03/2021**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402891201	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599871
689806701	FLIR footage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599864