

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/03/2021

Submitted Date:

12/07/2021

Document Number:

689806702

FIELD INSPECTION FORMLoc ID 316764 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 6720

Name of Operator: ROBERT L BAYLESS PRODUCER LLC

Address: 621 17TH ST STE 2300

City: DENVER State: CO Zip: 80293

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		notices@rlbayless.com	All inspections
thomas, john	505-326-2659	jthomas@rlbayless.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232726	WELL	PR	02/01/2021	OW	107-06140	DRY CREEK FEDERAL 1-14	SI

General Comment:

FLIR inspection in response to compliant 402880117. The complainant claimed emissions were observed at wellhead. COGCC FLIR inspection showed venting occurring at wellhead. Inspector left voicemail with Bayless on 12/7/2021 notifying them that venting must cease immediately. FLIR footage from the previous inspection, 7/19/2021 document number 689806021, also documented venting at the wellhead of this location. Well has been shut-in since the July inspection.

Inspected Facilities									
Facility ID:	232726	Type:	WELL	API Number:	107-06140	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: _____									
Corrective Action: _____ Date: _____									

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 40.395419 Long: -107.221811Wind: None Speed: (mph) Direction From: Weather: Clear Temperature: 42 (F)Assisting Staff: Emily Waldron Camera #: 3☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
10:50	AM	11:05	AM	Wellhead(s)

Comment: FLIR inspection in response to compliant 402880117. The complainant claimed emissions were observed at wellhead. COGCC FLIR inspection showed venting occurring at wellhead.Corrective Action: Immediately cease venting. Submit Form 4 for review and approval to vent.Date: 07/22/2021**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402891202	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599872
689806703	FLIR footage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5599865