

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/07/2021

Submitted Date:

12/07/2021

Document Number:

693506042

FIELD INSPECTION FORMLoc ID 326264 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10663

Name of Operator: ENDURING RESOURCES LLC

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

13 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------------|-------|-----------------------------------|-------------------------------------|
| Walter, Kyle | | kwalter@enduringresources.com | All Inspections |
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Huntington, Heather | | hhuntington@enduringresources.com | All Inspections per email 8/13/2021 |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 216136 | WELL | PR | 03/08/2002 | GW | 067-07742 | CHANEY 1-1 | PR |

General Comment:

Location

| | | | |
|--------------------|--------------------------------------|-------|------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Debris: Dead weeds along access road | | |
| Corrective Action | Comply with rule 606 | Date: | 01/07/2022 |

Overall Good: ☐

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | CONTAINERS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | |
| Corrective Action: | | Date: _____ |

| | | | |
|---------------------------|--|-------|------------|
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | Dead weeds in and around locaiton | | |
| Corrective Action: | Comply with rule 606 | Date: | 01/07/2022 |
| Type | OTHER | | |
| Comment: | Stained soil around gas motor | | |
| Corrective Action: | Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906 | Date: | 01/07/2022 |
| Type | OTHER | | |
| Comment: | Mechanical issue: gas motor appears to be leaking form motor and exhaust. | | |
| Corrective Action: | Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. | Date: | 01/07/2022 |
| Type | TRASH | | |
| Comment: | Wind wall material around motor in disrepair and laying on ground. | | |
| Corrective Action: | Comply with rule 606 | Date: | 01/07/2022 |

Overall Good: ☐

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|------------|-------|--|
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | Chain link | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Vertical Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 0 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 216136 Type: WELL API Number: 067-07742 Status: PR Insp. Status: PR**Producing Well**Comment: PRCorrective Action: Date: **BradenHead**Date of Last Brhd Test: 03/30/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date: **COGCC Comments**

| Comment | User | Date |
|--|---------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Tuesday December 7, 2021 at approximately 11:04AM I Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: Chaney #1-1</p> <p>Operator: Enduring resources</p> <p>API#: 067-07742</p> <p>Loc ID: 326264</p> <p>County: LaPlata</p> <p>While there, I observed a producing well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Debris: Rule 606 Corrective action date of 1-7-22 See photos 1,2,3,9,10</p> <p>Trash: Rule 606 Corrective action date of 1-7-22 See photo 5</p> <p>Stained soil: Rule 906 Corrective action date of 1-7-22 See photo 4</p> <p>Mechanical: Rule 608 e Corrective action date of 1-7-22 See photo 4</p> <p>Weather conditions: Cloudy</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | silverr | 12/07/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402891958 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5600535 |
| 693506043 | loc pic | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5600525 |