

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/07/2021

Submitted Date:

12/07/2021

Document Number:

693506050

FIELD INSPECTION FORM
 Loc ID 326289 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10663

Name of Operator: ENDURING RESOURCES LLC

Address: 6300 S SYRACUSE WAY, SUITE 525

City: CENTENNIAL State: CO Zip: 80111

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Huntington, Heather		hhuntington@enduringresources.com	All Inspections per email 8/13/2021
Walter, Kyle		kwalter@enduringresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216179	WELL	PR	08/27/1991	GW	067-07785	MONTOYA 10-2	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	01/07/2022
Type	WELLHEAD		
Comment:	Well sign burried buy gravel cannot see entire sign.		
Corrective Action:	Comply with rule 605	Date:	01/07/2022

Emergency Contact Number:		
Comment:		
Corrective Action:		Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil: around well head		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906	Date:	01/07/2022
Type	OTHER		
Comment:	Access: Well head is not accessable Surrounded by piles of gravel possible unsafe condition		
Corrective Action:	Comply with rule 602	Date:	01/07/2022
Type	OTHER		
Comment:	Mechanical issue: Electric HYD pump on well head appears to be leaking fluid.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	01/07/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:



Inspected FacilitiesFacility ID: 216179 Type: WELL API Number: 067-07785 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 04/01/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday December 7, 2021 at approximately 1:29PM I Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: Montoya #10-2</p> <p>Operator: Enduring resources</p> <p>API#: 067-07785</p> <p>Loc ID: 326289</p> <p>County: LaPlata</p> <p>While there, I observed a producing well site</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Mechanical issue: Rule 608 e Corrective action date of 1-7-22 See photo 3</p> <p>Stained soil: Rule 906 Corrective action date of 1-7-22 See photo 3</p> <p>Well sign: Rule 605 Corrective action date of 1-7-22 See photo 7</p> <p>Tanks signs: Rule 605 h Corrective action date of 1-7-22 see photo 4</p> <p>Well access: Rule 602 Corrective action date of 1-7-22 See photos 2,5,6,7</p> <p>This Well site is located in an active cement/ gravel facility.</p> <p>Weather conditions: Cloudy</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverr	12/07/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402891960	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5600537
693506051	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5600529