

Inspection Photos  
Operator: Morningstar  
API: 007-06211  
Date: 12/13/2021



Photo 1. View of the project area from the northwestern corner facing center.





Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with Indian ricegrass, crested wheatgrass, western wheatgrass, and rubber rabbitbrush. Pinyon and juniper trees growing along the edges of the project area.





Photo 3. View of the western project area from the southwestern corner facing northward.





Photo 4. View of erosional tunnel (approx. 1ft diameter) and channels (approx. 12in deep and 2-3ft wide), forming within the southwestern project area (facing up-slope).





Photo 5. View of reference area comprised of pinyon and juniper woodland with understory of sagebrush, Indian ricegrass, blue grama, James galleta, and cholla.