

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/07/2021

Submitted Date:

12/08/2021

Document Number:

693903953

**FIELD INSPECTION FORM**Loc ID 311892 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1001 17TH STREET STE 1160

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name      | Phone        | Email                       | Comment         |
|-------------------|--------------|-----------------------------|-----------------|
| Price, Andrew     | 918-260-8324 | aprice@arkomaops.com        | All Inspections |
| Recipient, Single |              | Inspections@catamountep.com | All Inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 259922      | WELL | PR     | 03/25/2002  | GW         | 067-08478 | DAVIS MV 1A   | RI          |
| 260634      | WELL | PR     | 03/18/2002  | GW         | 067-08481 | DAVIS FR 1A   | RI          |
| 296492      | WELL | PR     | 06/16/2008  | GW         | 067-09578 | IGS 155       | RI          |

**General Comment:**

On 12/7/2021 Catherine Roy conducted a reclamation and stormwater inspection. During this inspection the following compliance issues were observed:

Control weeds at the appropriate time, and no later than 6/1/2022. Subsequent monitoring and treatment are likely needed.

See below, and attached photos for additional detail.

**Inspected Facilities**Facility ID: 259922 Type: WELL API Number: 067-08478 Status: PR Insp. Status: RIFacility ID: 260634 Type: WELL API Number: 067-08481 Status: PR Insp. Status: RIFacility ID: 296492 Type: WELL API Number: 067-09578 Status: PR Insp. Status: RI

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment Approximately 200 Russian knapweeds observed along the access road. Revegetation is progressing within the interim reclamation areas.

Corrective Action Control weeds at the appropriate time, and no later than 6/1/2022. Subsequent monitoring and treatment are likely needed.

Date **06/01/2022**

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

|   |                 |                                 |                       |                     |                          |         |
|---|-----------------|---------------------------------|-----------------------|---------------------|--------------------------|---------|
| Overall Final Reclamation   |                 | Well Release on Active Location |                       | Multi-Well Location |                          |         |
| <b>Storm Water:</b>   |                 |                                 |                       |                     |                          |         |
| Loc Erosion BMPs  | BMP Maintenance | Lease Road Erosion BMPs         | Lease BMP Maintenance | Chemical BMPs       | Chemical BMP Maintenance | Comment |
|   |                 |                                 |                       |                     |                          |         |
| <div style="display: flex; justify-content: space-between;"> <div style="width: 70%;"> <p>Comment: Stormwater and erosion controls were assessed during this inspection and active erosion was not observed. Stormwater controls need to be monitored and maintained along the access road as part of a routine basis.</p> <p>Controls are assessed for whether they are functioning at the time of the inspection only. A determination as to whether or not they are adequate for the location over the duration of production is not made.</p> </div> <div style="width: 25%;"> <p>Date: _____</p> </div> </div> |                 |                                 |                       |                     |                          |         |
| <p>Corrective Action: _____</p>   |                 |                                 |                       |                     |                          |         |
| <p><b>Pits:</b>    <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT</p>   |                 |                                 |                       |                     |                          |         |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402893482    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5601786">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5601786</a> |
| 693903954    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5601768">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5601768</a> |