

Inspection Photos

API: 043-06142

Operator: JAVERNICK OIL

Inspection Date: 12/14/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-06142 | Date: 12/14/2021

Inspection Photos



Photo 1. Drone aerial photo facing southeast toward the abandoned well site. The area circled in blue was seeded and straw mulched. The remaining location circled in yellow was not reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/14/2021

Inspection Photos




Photo 2. Drone aerial photo facing west. The approximate disturbance area of the location is circled and only a portion of the location was reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/14/2021

Inspection Photos



Photo 3. Facing northeast toward the location. The trailer has been removed and soils are bare where the ytrailer was parked shown in the photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/14/2021

Inspection Photos



Photo 4. Facing northeast. The northern portion of the location was seeded and straw mulch. It is unknown if certified weed free straw was used.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/14/2021

Inspection Photos



Photo 5. Facing west at the location. The soils are lightly mulched and the mulch was not crimped into the soil which may blow away.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/14/2021

Inspection Photos



Photo 6. The shovel was placed into the soil to test for compaction. Soils seemed compacted down past 4 inches into the soil. Proper soil decompaction requires cross ripping to at least 18 inches.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/14/2021

Inspection Photos



Photo 7. Facing west at the location. The southern portion of the location was not reclaimed and consists of undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/14/2021

Inspection Photos



Photo 8. View of groundcover showing undesirable weeds (*Kochia* sp.).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/14/2021

Inspection Photos



Photo 9. Facing north toward the surrounding undisturbed reference area which consists of Blue grama prairie with little to no undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06142 | Date: 12/14/2021