

Inspection Photos

API: 043-40000

Operator: JAVERNICK OIL

Inspection Date: 12/14/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-40000 | Date: 12/14/2021

Inspection Photos



Photo 1. Facing east at the abandoned well site. There is an abandoned powerpole that remains which needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/14/2021

Inspection Photos



Photo 2. Facing south toward the location. There is gravelly soils that remain and the location is not reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/14/2021

Inspection Photos



Photo 3. There is cable and various debris that remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/14/2021

Inspection Photos



Photo 3. Facing north toward the location. There is gravelly soils that remain and the location is not reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/14/2021

Inspection Photos



Photo 5. There is a bridge timber used for the pumpjack base that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/14/2021

Inspection Photos



Photo 6. There are cement blocks that remain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40000 | Date: 12/14/2021