

Inspection Photos
location 430051
Inspection Date: 12/15/21
All Photos taken by Kris Neidel



12.14.2021 12:52

Photo #1 looking south from entry to pad at flare pit.



Inspection Photos
location 430051
Inspection Date: 12/15/21
All Photos taken by Kris Neidel



Photo #2 Close up of bottom of flare pit. It appeared that some soil was removed with an excavator bucket. No equipment from operations was observed in the pit (no flare, no flowline, etc)





Inspection Photos
location 430051
Inspection Date: 12/15/21
All Photos taken by Kris Neidel

Photo #3 area where separator was, the berm was pushed over on the northwest side.





Inspection Photos
location 430051
Inspection Date: 12/15/21
All Photos taken by Kris Neidel

Photo #4 looking mostly south at area of old tank battery, the far right of photo was north end of secondary containment.



Inspection Photos
location 430051
Inspection Date: 12/15/21
All Photos taken by Kris Neidel

Photo #5 piled up soil on south west edge of location. It was not obvious where the soil was from or what it was for.



Inspection Photos
location 430051
Inspection Date: 12/15/21
All Photos taken by Kris Neidel



Photo #6 looking north standing near the old tank battery, at two piles of soil.





Inspection Photos
location 430051
Inspection Date: 12/15/21
All Photos taken by Kris Neidel

Photo #7 north end of tankbattery, tire tracks were observable (heavy equipment)



Inspection Photos
location 430051
Inspection Date: 12/15/21
All Photos taken by Kris Neidel



Photo # looking northeast, the dark soil in snow on right is where the wellhead was.



Inspection Photos
location 430051
Inspection Date: 12/15/21
All Photos taken by Kris Neidel



Photo #9 close-up of the north most pile of soil.





Inspection Photos
location 430051
Inspection Date: 12/15/21
All Photos taken by Kris Neidel

Photo #10 middle pile of soil, this pile appeared to have cement.



Inspection Photos
location 430051
Inspection Date: 12/15/21
All Photos taken by Kris Neidel

Photo #11 soil and cement.





Inspection Photos
location 430051
Inspection Date: 12/15/21
All Photos taken by Kris Neidel

Photo #12 pile of cement. This pile can not be incorporated in any backfill





Inspection Photos
location 430051
Inspection Date: 12/15/21
All Photos taken by Kris Neidel

Photo #13 dark are in back 1/3 of photo is area of PA well and pumping unit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources