

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/09/2021

Submitted Date:

12/13/2021

Document Number:

689501323

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Brown, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
 Name of Operator: KP KAUFFMAN COMPANY INC
 Address: 1675 BROADWAY, STE 2800
 City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
-, Marcom		primarycontractor@marcomllc.net	
, KPK		cogcc@kpk.com	All Inspections
Gorka, Ray		RGorka@kpk.com	KPK environmental
Rickard, Jeff		JRickard@kpk.com	KPK environmental
Canfield, Chris		chris.canfield@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478086	SPILL OR RELEASE	CL	01/15/2021		-	UPRR 43 PAN AM G Consolidation #2	EI

General Comment:

This is an environmental inspection of Remediation Project 16131/Spill ID 478086 (CL). Any corrective actions from previous inspections that have not been addressed are still applicable.

At the time of inspection Operator and environmental contractor personal were on site to preform confirmation soil sampling.

Inspected Facilities

Facility ID: 478086 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: COGCC witnessed confirmation soil sampling on the excavation side walls. A third party contractor provided technical oversight for KPK crews during the sampling event. No stained soils were observed remaining insitu, but salt crusting was observed on excavation side walls near groundwater. An additional monitoring well had been installed east of the excavation area since the previous Form 27 submittal.

Corrective Action: See Form 27 Doc No. 402855541 conditions of approval Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402897312	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5605745