

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/03/2021

Submitted Date:

12/03/2021

Document Number:

700703632**FIELD INSPECTION FORM**Loc ID 334852 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211179	WELL	TA	10/01/2017	GW	045-06938	KRK 7-11	TA
264658	WELL	TA	06/01/2019	GW	045-08934	KRK 7-5D (K7)	TA
264659	WELL	PR	01/12/2003	GW	045-08935	KRK 7-11C (K7)	PR
264660	WELL	PR	07/01/2018	GW	045-08933	KRK 7-6D (D7)	PR

General Comment:**COGCC Inspection Report Summary**

On Friday 12/3/2021 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus K7, at Location # 334852 in Garfield county Colorado.

While there, I observed well was shut in. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Vertical unit separators includes 1 glycol storage tank, storage vessel contains no labeling to specify capacity or chemical hazard information.

2. Lack of battery signage.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lack of battery signage		
Corrective Action:	Comply with rule 605.e	Date:	02/04/2022
Type	OTHER		
Comment:	Vertical unit separators includes 1 glycol storage tank, storage vessel contains no labeling to specify capacity or chemical hazard information.		
Corrective Action:	Provide proper labeling	Date:	02/04/2022
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 4		corrective date
Comment:			
Corrective Action:		Date:	

Type: Vertical Heated Separator	# 4	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	500 gallon methanol tank in tank battery containment	
Corrective Action:		Date:
Type: Other	#	
Comment:	Two well are not on plunger lift	
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Inspector Name: Ramsey, Scott

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 211179 Type: WELL API Number: 045-06938 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Last MIT 7/12/2018

Corrective Action: _____ Date: _____

Facility ID: 264658 Type: WELL API Number: 045-08934 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Last MIT 7/12/2018

Corrective Action: _____ Date: _____

Facility ID: 264659 Type: WELL API Number: 045-08935 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action: _____ Date: _____

Facility ID: 264660 Type: WELL API Number: 045-08933 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402887106	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5596049
700703635	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5596046