

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/10/2021

Submitted Date:

12/13/2021

Document Number:

701600565

FIELD INSPECTION FORM

Loc ID 312251 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10017
Name of Operator: CHACO ENERGY COMPANY
Address: P O BOX 1587
City: DENVER State: CO Zip: 80201

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Nelson, Matt	303-981-3840	matt@chacoenergy.com	Inspections/Ops. Engineer

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219871	WELL	SI	05/15/2013	OW	075-07535	WRITEBOL 1	SI

General Comment:

[WO - RIG ON SITE - Preparing well to return to production. Investigating inability to pressure well. Casing leak suspected.](#)

Inspected Facilities

Facility ID: 219871 Type: WELL API Number: 075-07535 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Preparing well for MIT. Inspecting well for pressure loss and repairs. Packer staged down hole starting @ (2046'), well held pressure. Packer lowered to (2450'), well did not hold pressure.

Corrective Action: Repair and pass MIT or Plug well within (6) months from date of this FIR. Date: 06/13/2022

Workover

Comment: WO - Rig on Site - Investigating inability to pressure well. Suspected casing leak. Moving packer down hole, isolating leak depth.

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402898077	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5606412