

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/14/2021

Submitted Date:

12/15/2021

Document Number:

691201542

FIELD INSPECTION FORMLoc ID 440318 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		cogccinspection@pdce.com	
, Spills&Remediations		COGCCSpillRemediation@pdce.com	

General Comment:

This is an environmental inspection in response to the SRC Cannon Release reported by operator Form 19 (Document #402892427). Any corrective actions from previous inspections that have not been addressed are still applicable. Environmental subcontractor personnel reviewed site progress with COGCC inspector. After initial cleanup occurred Operator discovered historical contamination adjacent to the release. An excavation is open and ongoing, groundwater was observed infiltrating the base of excavation.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Good

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:	<u>Crews were continuing work, no fencing was present.</u>		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Work is proceeding under an Initial Form 27 for a release of produced water from a tank overflow. Based on site observations a second separate release has been discovered within a similar footprint.

Corrective Action: On the next supplemental Form 19 Operator shall provide details of secondary release as well as mitigation measures.

Date: 12/17/2021

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Other	Adequate		
Comment	No impacted material was being stored on site, excavation was ongoing.			
Corrective Action				Date: _____

Spill/Remediation:

Comment: Groundwater was observed infiltrating the base of the excavation for the historical release.

Corrective Action: Within 90 days of spill discovery (March 7, 2022), submit a Form 27 Site Investigation and Remediation Workplan with a proposed workplan and timeline for remediation of this Release.

Date: 03/07/2022

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402899496	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5607716
691201543	Historic Release Footprint	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5607707
691201544	Overflow Release Footprint	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5607708