

GOLDEN EAGLE 28-16 API# 05-071-07989 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: DECEMBER 17, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202115 AND 690201900



THE MAIN LEASE ROAD WAS SURFACED CROWNED TO CORRECT THE SURFACE EROSION AND CREATE SHEET FLOW. ROCK CHECK DAMS WERE PLACED IN THE FLOW LINE.

GOLDEN EAGLE 28-16 API# 05-071-07989 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: DECEMBER 02, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202115 AND 690201900



UPGRADIENT OF THE PORTION OF THE LEASE ROAD WHERE EROSION WAS OCCURRING, A WATER CALLOUT WAS INSTALLED TO REDUCE THE VOLUME OF RUN OFF ON THE ROADWAY SURFACE.

GOLDEN EAGLE 28-16 API# 05-071-07989 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: DECEMBER 02, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202115 AND 690201900



A WATER CALLOUT WAS INSTALLED TO REDUCE THE VOLUME OF RUN OFF ON THE ROADWAY SURFACE.

GOLDEN EAGLE 28-16 API# 05-071-07989 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: DECEMBER 02, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202115 AND 690201900



THE WATER CALLOUT TERMINATES INTO RIP-RAP.

GOLDEN EAGLE 28-16 API# 05-071-07989 – OGRIS OPERATING LLC  
OGCC OPERATOR NUMBER 10758 - DATE: DECEMBER 17, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202115 AND 690201900



GRAVEL WAS PULLED OFF OF THE EDGE OF THE ROADWAY BACK ONTO THE DRIVING SURFACE.