

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /28SWSW

Location ID: 335446



Photo #5518 from entrance to location.



Photo #5519 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /28SWSW

Location ID: 335446



Photo #5520 Storage tank not labeled.



Photo #5521 Sight glass indicates the storage tank is full of an unknown fluid.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /28SWSW

Location ID: 335446



Photo #5522 Location lacks stabilization.



Photo #5523 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /28SWSW

Location ID: 335446



Photo #5524 Insufficient tracking BMP at entrance to location.