

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402904510

Date Received:
12/20/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758

Name of Operator: OGRIS OPERATING LLC

Address: PO BOX 53467

City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Gee, Greg</u>	<u>903-987-0353</u>	<u>ggee@ogrisop.com</u>
<u>ATWATER BONNIE</u>		<u>batwater@ogrisop.com</u>
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>efitzgerald@ogrisop.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 690202036

Inspection Date: 09/03/2021

FIR Submit Date: 09/07/2021

FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC

Company Number: 10672

Address: 6295 GREENWOOD PLAZA BLVD #100

City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308031

Location Name: APACHE CANYON-634S68W Number: 13SWSE County: LAS ANIMAS

Qtrqtr: SWSE Sec: 13 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.080550 Longitude: -104.944060

FACILITY - API Number: 05-071-00 Facility ID: 260248

Facility Name: APACHE CANYON Number: 13-15

Qtrqtr: SWSE Sec: 13 Twp: 34S Range: 68W Meridian: 6

Latitude: 37.080550 Longitude: -104.944060

CORRECTIVE ACTIONS:

1 CA# 155541

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 12/23/2020

Response: CA COMPLETED

Date of Completion: 11/05/2021

Operator Comment: THE ROAD SURFACE WAS REGRADED AND CROWNED. THIS CONFIGURATION WILL CREATE SHEET FLOW AND ELIMINATE THE TIRE RUTS/SURFACE EROSION. THE ROAD SURFACE WAS COMPACTED BY UTILIZING A VIBRATION SOIL COMPACTION ROLLER TO PROVIDE STABILIZATION. CULVERTS WERE

MAINTAINED, SEDIMENT ACCUMULATION REMOVED. THE BAR DITCH WAS DOMINATED TO RECEIVE STORMWATER RUN OFF FROM THE ACCESS ROAD AND DIRECT RUN OFF TO THE CULVERT INLETS.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: Sr. Environmental Tech.

Date: 12/20/2021 11:02:39 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402904510	FIR RESOLUTION SUBMITTED
402904530	PHOTO LOG

Total Attach: 2 Files