

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/23/2021

Submitted Date:

12/31/2021

Document Number:

701004186**FIELD INSPECTION FORM**Loc ID 314192 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 5115Name of Operator: AUSMUS & CLARK OILAddress: 34809 ROAD 17City: HOLLY State: CO Zip: 81047**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Clark, Keith	719-688-2319	klclark@cminet.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
227884	WELL	SI	04/01/2020	OW	099-06211	DENT 1-16	SI

General Comment:[Routine Inspection](#)

Location				
Lease Road:				
Type	Access			
comment:	Dirt road through farm ground			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	Stickers on tanks. Oil tank labels missing			
Corrective Action:	Install sign to comply with Rule 605.h.			Date: 01/23/2022
Type	BATTERY			
Comment:	Lease sign mounted to stairs at tank battery			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Dead weeds across location			
Corrective Action:	Comply with Rule 606			Date: 01/23/2022
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Wire fence around unit, wellhead and tank battery. Fence is in disrepair			
Corrective Action:	Repair or remove fencing			Date: 01/23/2022
Equipment:				
Type: Flare	# 0			corrective date
Comment:	Trash barrel is removed at time of inspection			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:	Continental unit			
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Kohler gas engine			

Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Gas scrubber ad propane tank on trailer		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	<100 BBLS	STEEL AST		38.134510,-102.582400
Comment:	60bbl Steel tank used as gun barrel (silver)				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shared berms			
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	FIBERGLASS AST		38.134510,-102.582400
Comment:	North tank is oil tank (tan)				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	FIBERGLASS AST		38.134510,-102.582400
Comment:	South tank (green)				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	

Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: Shared berms					
Corrective Action:				Date:	
Venting:					
Yes/No					
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities			
Facility ID: 227884	Type: WELL	API Number: 099-06211	Status: SI
		Insp. Status: SI	
Producing Well			
Comment:	Producing. Not pumping at time of inspection		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701004249	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5621963