

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/03/2022

Submitted Date:

01/04/2022

Document Number:

688801092

FIELD INSPECTION FORM

 Loc ID 326514 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments2 Number of Corrective Actions

-
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**Contact Information:**

Contact Name	Phone	Email	Comment
Killough, Mitch		mkillough@hilcorp.com	
Shorty, Priscilla	505-324-5188	pshorty@hilcorp.com	All Inspections SW
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89127	WELL	PR	01/01/2003	GW	067-08231	HUBER-LENGAL/SLAUGHTER 2-10	EI

General Comment:

On January 3, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Energy Co. Huber-Lengal/Slaughter #2-10. For the most recent field inspection report of this facility, please refer to document #693506028.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign mounted to separator shack. Sign is not compliant with Rule 605.d.		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 03/04/2022
Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	Stained gravel and concrete pad at well head and near prime mover.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 02/04/2022
In Containment: No			
Comment:			
<input checked="" type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Sound walls around pump jack. Guard fencing present.		
Corrective Action:			Date:
Equipment:			
Type: Vertical Separator	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 3		
Comment:	SE marker not observed during this inspection.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Natural gas powered.		
Corrective Action:			Date:

Type: Bradenhead	# 1		
Comment:	Access at surface.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	In separator shack.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 89127 Type: WELL API Number: 067-08231 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On January 3, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Energy Co. Huber-Lengal/Slaughter #2-10. For the most recent field inspection report of this facility, please refer to document #693506028. Stained concrete and gravel were observed near the prime mover and exhaust piping during this inspection. The location sign mounted to the separator shack is not compliant with Rule 605.d.	hughesjo	01/04/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688801093	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5623882