

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/21/2021

Submitted Date:

12/29/2021

Document Number:

688311750

FIELD INSPECTION FORM

Loc ID: 305047 Inspector Name: Sherman, Susan On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Foundation Energy	(866) 767-3600	regulatory@foundationenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277701	WELL	PR	02/08/2006	GW	125-09293	PRATHER 21-12	PR

General Comment:

Reinspection-passed, 2021 gas meter calibration card is present

Inspected Facilities

Facility ID: 277701 Type: WELL API Number: 125-09293 Status: PR Insp. Status: PR

Producing Well

Comment: [pr 10/1/2021 production is reported to COGCC database.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					

Comment: Continued stuffing box leak at wellhead cause produced water to leave location (under fence at wellhead) and eroded into pasture (see attached photos).

Corrective Action: Install or repair required BMPs per Rule 1002.f(2)C

Date: 01/13/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402912345	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5620028
688311816	Foundation Energy Prather 21-12 REIN	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5619998