

Inspection Photos
Operator: Arkoma
API: 067-08793
Date: 12/22/2021



Photo 1. View of the southern project area from the southwestern corner facing center. Revegetation is progressing with western wheatgrass, smooth brome, and intermediate wheatgrass. Revegetation at final reclamation needs to be representative of the surrounding reference area.



Photo 2. View of the western fill slope from the southwestern corner facing northward.



Photo 3. View of erosional channel approximately 12-15 inches wide and deep, flowing off of the well pad and down/across the access road.



Photo 4. View of Russian thistle debris observed within the project area, near the well pad entrance, needs to be removed.



Photo 5. View of area along access road (approx. 10 -15 feet long) where stormwater flows over the access road and is eroding the edges of the road. Cobble and gravel from the road observed washed down-slope. Drainage and road need stabilization here.



Photo 6. View of the reference area comprised of pinyon and juniper woodland with sagebrush, James galleta, purple threeawn, and Indian ricegrass.