

Lorencito 9-5-34-66





Repaired berm wall in front of tank





Repaired berm wall in front of tank





Installed appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1),(2).