

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/03/2022

Submitted Date:

01/04/2022

Document Number:

688801090

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
Hughes, Jim _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

2 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		sjninspections@ikavenergy.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258190	WELL	PR	08/14/2001	GW	067-08334	ROY ANNALA A 2	EI

General Comment:

On January 3, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Simcoe LLC Roy Annala A #2. For the most recent field inspection report of this facility, please refer to document #693901733. This site visit was conducted to assess Spill/Release Point ID #481340.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Free standing sign near PBV.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	Concrete pad for pump jack is stained and wet near prime mover.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a		Date: 02/04/2022
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Sound walls around pump jack. Guard fencing present.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sound walls around compressor.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Perimeter fencing.		
Corrective Action:		Date:	
Equipment:			
Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Natural gas powered.		
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV STEEL		37.220742,-107.746466
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	21 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
067-08334

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 258190 Type: WELL API Number: 067-08334 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass			Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On January 3, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Simcoe LLC Roy Annala A #2. For the most recent field inspection report of this facility, please refer to document #693901733. This site visit was conducted to assess Spill/Release Point ID #481340.</p> <p>Areas of melted snow on and off location apparently signify direction of flow and extent of release area. Submit analytical results upon receipt via a Supplemental Form 19.</p> <p>The concrete pad beneath the prime mover is wet and stained.</p>	hughesjo	01/04/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402916431	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5623831
688801091	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5623830