

Inspection Photos
Operator: Simcoe
API: 067-07621
Date: 1/11/2022



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing here with rubber rabbitbrush, crested wheatgrass, and smooth brome.



Photo 3. View of trailers stored on the northern portion of the well pad. This portion of the well pad is not in use for production operations and needs interim reclamation.



Photo 4. View of reference area, comprised of pinyon and juniper woodland with prickly pear, squirrel tail, blue grama, and sagebrush in the understory.