

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/10/2022

Submitted Date:

01/12/2022

Document Number:

689806913

**FIELD INSPECTION FORM**Loc ID 324757 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10598

Name of Operator: SANDRIDGE EXPLORATION &amp; PRODUCTION LLC

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Boyer, David	303-994-0000	david@d90energy.com	
Inspections, General		sandridgeenvironmental@san dridgeenergy.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298046	WELL	PR	03/01/2020	OW	057-06472	MUTUAL 7-17H	PR
444868	WELL	PR	02/01/2021	OW	057-06541	Mutual 0780 4-8H	SI
444869	WELL	PR	10/17/2016	OW	057-06542	Castle 0780 1-17H20	PR
444870	WELL	PR	08/01/2020	OW	057-06543	Mutual 0780 3-8H	SI
444871	WELL	PR	08/05/2016	OW	057-06544	Mutual 0780 2-8H	SI
444874	WELL	PR	10/01/2020	OW	057-06547	Hebron 0780 3-18H	PR
445017	WELL	PR	10/14/2016	OW	057-06553	Hebron 0780 4-18H	PR

**General Comment:**

Routine FIU inspection.

Form 9 to transfer from Sandridge to D90 received 5/12/2021 document number 402676753, form remains In Process. Compliance issue observed:  
equipment stored on location

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s). Well signs must contain: the well name, the API number, and the legal location including the quarter/quarter section.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Tank battery sign incomplete. Tank Battery sign must include: operator name, telephone number where operator can be reached at all times, telephone number for local emergency services (911 where available), the public road used to access the site, well name, API numbers, and legal location for all wells associated with battery, location of battery including the quarter/quarter section.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-638-6096

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Equipment stored on location.		
Corrective Action:	Comply with Rule 606.	Date:	02/14/2022

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 8		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 8		
Comment:			
Corrective Action:		Date:	

Type: Emission Control Device	# 2	
Comment:		
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Generator	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 298046 Type: WELL API Number: 057-06472 Status: PR Insp. Status: PR

**Producing Well**Comment: Corrective Action: Date: 

Facility ID: 444868 Type: WELL API Number: 057-06541 Status: PR Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In☐ Temporarily AbandonedReminder: Comment: Corrective Action: Date: 

Facility ID: 444869 Type: WELL API Number: 057-06542 Status: PR Insp. Status: PR

**Producing Well**Comment: Corrective Action: Date: 

Facility ID: 444870 Type: WELL API Number: 057-06543 Status: PR Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In☐ Temporarily AbandonedReminder: Comment: Corrective Action: Date: 

Facility ID: 444871 Type: WELL API Number: 057-06544 Status: PR Insp. Status: SI

**Idle Well**Purpose: ☒ Shut In☐ Temporarily AbandonedReminder: Comment: Corrective Action: Date: 

Facility ID: 444874 Type: WELL API Number: 057-06547 Status: PR Insp. Status: PR

**Producing Well**Comment: Corrective Action: Date: 

Facility ID: 445017 Type: WELL API Number: 057-06553 Status: PR Insp. Status: PR

**Producing Well**Comment: Corrective Action: Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Snow cover inhibited scope of stormwater inspection. No apparent soil migration; erosion or soil movement. Full stormwater inspection will be performed after snowmelt.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402924529	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5631287">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5631287</a>
689806914	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5631275">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5631275</a>