

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/18/2022

Submitted Date:

01/21/2022

Document Number:

701004345

**FIELD INSPECTION FORM**

Loc ID 418902 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10699  
Name of Operator: OWN RESOURCES OPERATING LLC  
Address: 38 PALMER CREST CT  
City: SPRING State: TX Zip: 77381

**Findings:**

10 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
418903	WELL	SI	08/01/2021	GW	125-11917	SG Hagemann 41-12 1S45W	SI

**General Comment:**

[Routine Inspection](#)

Location				
<b>Lease Road:</b>				
	Type Access			
	comment: Gravel road through pasture			
Corrective ActionL				Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
	Type WELLHEAD			
	Comment: Lease sign mounted to fence at meter shed			
Corrective Action:				Date:
Emergency Contact Number:				
	Comment: <input style="width: 100%;" type="text"/>			
	Corrective Action: <input style="width: 100%;" type="text"/>			Date: _____
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
	Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
	Type OTHER			
	Comment: Metal panels around meter shed			
Corrective Action:				Date:
	Type WELLHEAD			
	Comment: Metal panels around wellhead			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Gas Meter Run	# 1			corrective date
	Comment: Meter shed is on south side of wellhead			
Corrective Action:				Date:
Type: Ancillary equipment	# 2			
	Comment: Control panel and telemetry equipment			
Corrective Action:				Date:
Type: Vertical Separator	# 1			
	Comment: Vertical gas separator 50% buried by meter shed			
Corrective Action:				Date:
Type: Progressive Cavity	# 1			
	Comment: Weatherford cavity			
Corrective Action:				Date:

Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 418903 Type: WELL API Number: 125-11917 Status: SI Insp. Status: SI

**Producing Well**

Comment: [Producing. Casing production](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701004366	location photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5641074">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5641074</a>