

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/05/2022

Submitted Date:

01/05/2022

Document Number:

699304755**FIELD INSPECTION FORM**Loc ID 311352 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	<a href="#">All Inspections</a>
,		dnr_cogccenforcement@state.co.us	
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245730	WELL	PR	03/01/2020	GW	123-13525	HARRY EWING C 1	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>		
Type	UNUSED EQUIPMENT	
Comment:	unused meter box and transformer,	
Corrective Action:	Comply with Rule 603.f,new rule # is 606	Date: 10/17/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>		
Type	PUMP JACK	
Comment:	steel pie and angle iron	
Corrective Action:		Date:
Type	OTHER	
Comment:	ancillary equipment has steel pipe and round stock	
Corrective Action:		Date:

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel, Meter box and transformers		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	



**Inspected Facilities**Facility ID: 245730 Type: WELL API Number: 123-13525 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 10/28/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 1/5/2022 at approximately 1235 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman, location: Harry Ewing C #1 API #05-123-13525 in Weld County Colorado. While there, I observed a producing wellsite. This is a follow up inspection per Doc. # 699303776.</p> <p>During this inspection the following compliance issue has not been addressed and is delinquent:</p> <p>603.f Unused equipment: unused electric transformers and meter box, CA date 10/17/2019 see photo #5. This CA has been wrote up for the past 3 inspections and has not been addressed and will be turned over to COGCC enforcement.</p> <p>Location is muddy and partly snow covered, weather is clear, cloudy and cold.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	revasr	01/05/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402918280	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5625500">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5625500</a>
699304756	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5625496">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5625496</a>