

Inspection Photos
Operator: Simcoe
API: 067-07862
Date: 1/24/2022



Photo 1. View of project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern project area facing northward. Revegetation is progressing with irrigated grasses such as tall fescue and timothy.




Photo 3. View of the weedy kochia debris observed on the well pad and in the reclamation area.



Photo 4. View of more kochia debris observed around fired equipment and within the outer edges of the working area.



Photo 5. View of reference area vegetation comprised of grasses such as irrigated grass field, with timothy, tall fescue, and meadow brome.