

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/13/2022

Submitted Date:

01/19/2022

Document Number:

688801096

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 Hughes, Jim _____ 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:
 OGCC Operator Number: 10766
 Name of Operator: ARKOMA OPERATIONS LLC
 Address: 2121 S COLUMBIA AVE SUITE 101
 City: TULSA State: OK Zip: 74114
Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Price, Andrew	918-260-8324	aprice@arkomaops.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
412668	GAS PROCESSING PLANT	AC	03/30/2021		-	IGNACIO GAS PLANT	EI
481399	SPILL OR RELEASE	AC			-	Ignacio Gas Plant	EI

General Comment:

On January 13, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Arkoma Operations LLC Ignacio Gas Plant, Facility ID #412668. This site visit was in response to Spill/Release Point ID #481399. Arkoma personnel were on site during this field inspection.

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Free standing sign near facility entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Perimeter fencing, sound walls.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		37.105398,-107.772175
Comment:	Frozen valve on tank resulted in Spill/Release #481399.				
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.				Date: 02/02/2022

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 412668 Type: GAS API Number: - Status: AC Insp. Status: EI

Facility ID: 481399 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 240

Comment: [See Spill/Release Point ID #481399 for more information regarding this release.](#)Corrective Action: [Control and contain spills/releases and clean up per Rule 912.a.](#)

Date: 02/18/2022

Reportable: YES

GPS: Lat 37.105453

Long -107.772203

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment	User	Date
On January 13, 2022 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Arkoma Operations LLC Ignacio Gas Plant, Facility ID #412668. This site visit was in response to Spill/Release Point ID #481399. Arkoma personnel were on site during this field inspection. During this inspection a crew was removing ice from within the secondary containment berm.	hughesjo	01/19/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402930934	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5638544
688801097	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5638527