

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/18/2022

Submitted Date:

01/18/2022

Document Number:

699804013

FIELD INSPECTION FORM

Loc ID 324283	Inspector Name: De Paolo, Corey	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 10433 Name of Operator: LARAMIE ENERGY LLC Address: 1001 17TH STREET #1900 City: DENVER State: CO Zip: 80202				Findings: 8 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273551	WELL	PR	01/01/2005	GW	045-10258	OXY FEDERAL 708-11	PR

General Comment:**COGCC Inspection Report Summary**

On Friday 1/14/22 at approximately 13:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at LARAMIE ENERGY LLC OXY Federal /0708-11 Pad, Location #324283 in Garfield County Colorado.
While there, I observed normal production operations.
During this inspection the following compliance issues were observed:

1) Separator units include an attached storage tank. The storage tank is approximately 2'x3'x10' with an approximate capacity of 11 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank with a corrective action date of 3/14/22.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location

Overall Good: ☒

Signs/Marker:

Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x10' with an approximate capacity of 11 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:	Identify all hazards associated with equipment.	Date:	03/14/2022
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-248-0497

Corrective Action:

Date: _____

Overall Good: ☒

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:

Type: Bradenhead	# 1		corrective date
Comment:	Taylor plug located on braden head. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		

Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 273551	Type: WELL	API Number: 045-10258	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:

--	--	--	--	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Berms						
Sediment Traps						
		Sediment Traps				
		Berms				
		Culverts				
Gravel						
		Ditches				
Ditches						
		Compaction				

Comment: Limited storm water inspection due to location being covered with snow. Location appears to have been plowed within the confines of the BMP's of location.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Sign/markers for corrective actions.	depaoloc	01/18/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402930608	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5638197
699804014	Photos for Insp. #699804013	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5638190