

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/26/2022

Submitted Date:

01/26/2022

Document Number:

695105563

FIELD INSPECTION FORM

 Loc ID 309467 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10758
 Name of Operator: OGRIS OPERATING LLC
 Address: PO BOX 53467
 City: MIDLAND State: TX Zip: 79710
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
WARD, GIENA	719-859-1394	gward@ogrisop.com	All Inspections
GEE, GREG	903-987-0353	ggee@ogrisop.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295527	WELL	PR	08/01/2011	GW	071-09570	APACHE CANYON 04-15	PR
300258	PIT		12/16/2008		-	APACHE CANYON 04-15	

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 4: LARGE AREA OF IMPACTED SOIL AROUND COMPRESSOR (APPEARS TO BE OILY WASTE FROM LEAKING EQUIPMENT). PHOTO 5: AREA OF IMPACTED SOIL AROUND PRIME MOVER ENGINE SKID (APPEARS TO BE OILY WASTE FROM LEAKING EQUIPMENT).		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002. (2).D.		Date: <u>02/02/2022</u>

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:	PHOTO 9: Vacuum pump observed on well without COGCC approval.		
Corrective Action:	Provide COGCC with documentation showing approval of use of vacuum pump.		Date: <u>02/15/2022</u>
Type: Prime Mover	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			

Corrective Action:		Date:	
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: [PHOTO 7: OILY WASTE IN PRIME MOVER ENGINE SKID. COMPLY WITH RULE 1002.f. \(2\)B,](#)
[PHOTO 8: OILY WASTE IN COMPRESSOR SKID.](#)

Corrective Action: [Comply with general provisions of the oil and gas act for wildlife protection AND SB-181.](#)

Date: 01/27/2022

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 300258 Lat: 37.108370 Long: -104.891300

Reference Point: SE Other: _____ Length: 80 Width: 40

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action

Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment: _____

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: NONE

Corrective Action

Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: _____

Corrective Action

Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	300258	1841332	

COGCC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #698701889. THIS IS THE SECOND NOTICE IN THE LAST 16 MONTHS FOR IMPACTED SOIL AROUND LEAKING EQUIPMENT ON LOCATION.	beardslt	01/26/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695105564	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5645673