

Inspection Photos
Operator: Logos
API: 067-05601
Date: 1/27/2022



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the the southwestern corner facing eastward. Revegetation appears to be progressing with sand dropseed, western wheatgrass, and smooth brome.



Photo 3. View of the western project area from the southern corner facing northeastward.



Photo 4. View of reference area comprised of pinyon and juniper mixed with big sagebrush, saltbush, smooth brome, and Indian ricegrass.