

Inspection Photos
Operator: Simcoe
API: 067-07471
Date: 1/27/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass, Indian ricegrass, and rubber rabbitbrush.



Photo 3. View of southern project area from the southeastern corner facing westward.



Photo 4. View of erosional tunneling occurring where concentrated stormwater flows off of the northeastern corner of the well pad around and below a cobble BMP that is not functioning properly.



Photo 5. View of reference area comprised of pinyon and juniper mixed with big sagebrush, James galleta, yucca, and Indian ricegrass.