

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2022

Submitted Date:

01/25/2022

Document Number:

700703770**FIELD INSPECTION FORM**Loc ID 324008 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211477	WELL	PR	03/15/2001	GW	045-07237	VASSAR/HEATH RMV 99-28	PR

**General Comment:****COGCC Inspection Report Summary**

On Monday 1/24/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RMV 99-28, at Location # 324008 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

Location and access are snow covered at the time of inspection. Location is plowed in a path.

During this inspection the following possible compliance issues were observed:

1. Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.
2. Load line missing bull plug/cap

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Snow covered/plowed			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	OTHER			
Comment:	1. Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	Load line missing bull plug/cap			
Corrective Action:	Comply with rule 603.i.			Date: 03/04/2022
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
Type: Bird Protectors	# 2			corrective date
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 2			
Comment:				

Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				
			Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:			
		Date:	

Inspected Facilities									
Facility ID:	211477	Type:	WELL	API Number:	045-07237	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited storm water inspection due to snow cover

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402936811	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5644043">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5644043</a>
700703778	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5644026">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5644026</a>