

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32NWSE

Location ID: 335103



Photo #5818 from entrance to location.



Photo #5819 Vent pipe on tank open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32NWSE

Location ID: 335103



Photo #5820 Location lacks stabilization.



Photo #5821 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32NWSE

Location ID: 335103



Photo #5822 Insufficient tracking BMP located at the entrance to location.