

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2022

Submitted Date:

01/24/2022

Document Number:

699804047

FIELD INSPECTION FORM

 Loc ID 334982 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: PO BOX 370
 City: PARACHUTE State: CO Zip: 81635
Findings:

- 21 Number of Comments
 2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257667	WELL	PR	07/24/2000	GW	045-07590	FEDERAL GM 31-11	PR
273091	WELL	PR	11/20/2004	GW	045-10219	FEDERAL GM 431-11	PR
273092	WELL	PR	11/21/2004	GW	045-10218	FEDERAL GM 331-11	PR
273127	WELL	PR	11/21/2004	GW	045-10220	FEDERAL GM 531-11	PR

General Comment:

COGCC Inspection Report Summary

On Monday 1/24/22 at approximately 11:30 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /11NWNE, Location #334982 in Garfield County Colorado.

Refer to document #699803570 inspection conducted on 8/17/21. All previous corrective actions have been completed.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- 1) Vent pipe on tank open ended with a corrective action date of 1/31/22.
- 2) Location lacks stabilization. Insufficient tracking BMP at entrance to location with a corrective action date of 2/8/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is approximately 2'x3'x14' with an approximate capacity of 15 bbl. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:		corrective date
Type: Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 4	
Comment:	All wells on plunger lift	
Corrective Action:		Date:
Type: Bradenhead	# 4	
Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.	
Corrective Action:		Date:
Type: Gas Meter Run	# 4	
Comment:		
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Vent pipe on tank open ended.	
Corrective Action:	Operators will prevent and minimize adverse impacts to wildlife resources.	Date: 01/31/2022
Type: Ancillary equipment	# 1	
Comment:	Chemical tank	
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	<u>257667</u>	Type:	<u>WELL</u>	API Number:	<u>045-07590</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:								Date:	
Facility ID:	<u>273091</u>	Type:	<u>WELL</u>	API Number:	<u>045-10219</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:								Date:	
Facility ID:	<u>273092</u>	Type:	<u>WELL</u>	API Number:	<u>045-10218</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:								Date:	
Facility ID:	<u>273127</u>	Type:	<u>WELL</u>	API Number:	<u>045-10220</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing</u>								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Other	Fail					Insufficient tracking BMP at entrance to location
		Culverts				
Sediment Traps						
		Check Dams				
				Material Handling And Spill Prevention		Chemical tank
Gravel	Fail					Gravel insufficient
Compaction	Fail					Location lacks stabilization.
		Gravel				
		Berms				
		Ditches				
Ditches						
		Sediment Traps				

Comment: Location lacks stabilization. Insufficient tracking BMP at entrance to location.

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 02/08/2022

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Equipment and Storm water for corrective actions.	depaoloc	01/24/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402939348	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5646664
699804048	Photos for Insp. #699804047	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5646654