

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SWSE

Location ID:



Photo #5870 from entrance to location.



Photo #5871 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SWSE

Location ID:



Photo #5872 Location lacks stabilization.



Photo #5873 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SWSE

Location ID:




Photo #5874 Insufficient tracking BMP located at the entrance to location.