

Inspection Photos
Operator: Simcoe
API: 067-09482
Date: 2/11/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with smooth brome, crested wheatgrass, and western wheatgrass.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. Erosional channel approx. 1ft wide and 2.5ft deep observed in the western project area, deepening as it flows toward the edge of the project area. Stabilization measures are needed here.



Photo 5. View of reference area comprised of sagebrush shrubland with Indian ricegrass, squirreltail, blue grama, and snakeweed.