

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/18/2022

Submitted Date:

02/18/2022

Document Number:

699804181**FIELD INSPECTION FORM**Loc ID 324108 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**15 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257370	WELL	PR	05/15/2000	GW	045-07551	FEDERAL PA 22-32	PR

**General Comment:****COGCC Inspection Report Summary**

On Friday 2/18/22 at approximately 11:30 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /32SENW, Location #324108 in Garfield County Colorado.

Refer to document #699803659 inspection conducted on 9/27/22. All previous corrective actions have been completed.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) Location lacks stabilization. Insufficient tracking BMP at entrance to location with a corrective action date of 3/5/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.				
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 1				
Comment:					
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 257370	Type: WELL	API Number: 045-07551	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps				
		Ditches				
Gravel	Fail					Gravel insufficient
				Material Handling And Spill Prevention		chemical tank
		Culverts				
		Berms				
Berms						
Compaction	Fail					Location lacks stabilization.
Other	Fail					Insufficient tracking BMP at entrance to location
Ditches						
		Compaction	Fail			Access road lacks stabilization.
		Gravel				
Sediment Traps						

Comment: Location lacks stabilization. Insufficient tracking BMP at entrance to location.Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.Date: 03/05/2022Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<u>Refer to Stormwater for corrective actions.</u>	depaoloc	02/18/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699804182	Photos for Insp. #699804181	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5668591">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5668591</a>