

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/18/2022

Submitted Date:

02/19/2022

Document Number:

701102704

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: LONGWORTH, MIKE On-Site Inspection
 316160 _____ 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 _____ 5 Number of Comments
 _____ 1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10539
 Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
 Address: 760 HORIZON DRIVE STE 400
 City: GRAND JUNCTION State: CO Zip: 81506

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|-------------------------------------|
| Gas, UtahGasCorp | 970-693-6021 | inspections@utahgascorp.com | Inspection mail box |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 89335 | WELL | PR | 06/01/2020 | GW | 103-09928 | LOWER HORSE DRAW UNIT 2181 | PR |

General Comment:
[COGCC Routine Inspection Report Summary](#)
 Location is in a High Priority Habitat Area.
 During this inspection the following compliance issues were observed:
 • No well name and legal description at well
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---|-------|------------|
| Type | WELLHEAD | | |
| Comment: | No well name and legal description at well. | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | Date: | 05/20/2022 |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|-----|-------|--|
| Comment: | 911 | Date: | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|-------|-------|--|
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|--------------|-------|--|
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Equipment:

| Type: | | # | | corrective date |
|--------------------|--|-----|-------|-----------------|
| Gas Meter Run | | # 1 | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Bradenhead | | # 1 | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |
| Plunger Lift | | # 1 | | |
| Comment: | | | | |
| Corrective Action: | | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|----------|---------|--------|
| CONDENSATE | 1 | <50 BBLs | Open Top | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | 45 bbl |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | |
|--------------------|----|
| Yes/No | NO |
| Comment: | |
| Corrective Action: | |
| Date: | |

Flaring:

| | |
|--------------------|--|
| Type | |
| Comment: | |
| Corrective Action: | |
| Date: | |

Inspected Facilities

Facility ID: 89335 Type: WELL API Number: 103-09928 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | | | | | | |
| | | Ditches | | | | |
| | | Culverts | | | | |
| | | Compaction | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 701102709 | Inspection 701102704 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5669175 |