

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/11/2022

Submitted Date:

02/13/2022

Document Number:

702100002

FIELD INSPECTION FORM

 Loc ID 334116 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10705
 Name of Operator: EVERGREEN NATURAL RESOURCES LLC
 Address: 1875 LAWRENCE ST STE 1150
 City: DENVER State: CO Zip: 80202
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 9 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|-------------------------|--------------|----------------------------|---------------------------------|
| Distribution, Evergreen | 719-846-7898 | cogcc.evergreen@enrllc.com | All Inspections |
| Kosola, Jason | | jason.kosola@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 284893 | WELL | PR | 10/01/2017 | GW | 071-08805 | STARBUCKS 42-34 | PR |
| 284894 | WELL | PR | 09/10/2006 | GW | 071-08806 | STARBUCKS 42-34 TR | PR |

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|--|------------------|
| Type | OTHER | | |
| Comment: | PHOTO 5: PACKING ON ORIGINAL WELLHEAD IS LEAKING. PHOTO 6: PRODUCED WATER TRAVELED APP150' ACROSS LOCATION TO THE EAST. PHOTO 7: PRODUCED WATER TRAVELED APP.50' ACROSS LOCATION TO THE SOUTH AND SOUTH EAST. | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 912.a. Control and contain spills/releases and clean up per Rule 912.a. operator was on location before I finished my inspection. | | Date: 02/12/2022 |
| Type | UNUSED EQUIPMENT | | |
| Comment: | PHOTO 4: UNUSED EQUIPMENT (SOUND WALL NEAR ORIGINAL WELL). REMOVE UNUSED EQUIPMENT, COMPLY WITH RULE 606. 3-18-22. | | |
| Corrective Action: | | | Date: |

Overall Good:

| Spills: | | | |
|----------------|------|--------|--|
| Type | Area | Volume | |
| | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

| Equipment: | | | corrective date |
|---------------------------|--|--|-----------------|
| Type: Gas Meter Run | # 2 | | |
| Comment: | BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR. | | |
| Corrective Action: | | | Date: |
| Type: Vertical Separator | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 2 | | |
| Comment: | both are accessable | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Deadman # & Marked | # 6 | | |
| Comment: | | | |

| | | | |
|--------------------------|----------------|-------|--|
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | electric drive | | |
| Corrective Action: | | Date: | |
| Type: Progressive Cavity | # 1 | | |
| Comment: | electric drive | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 284893 Type: WELL API Number: 071-08805 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/22/2011 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 284894 Type: WELL API Number: 071-08806 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/22/2011 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

03/13/2022

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402955118 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5663384 |
| 702100003 | insp. photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5663381 |