

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/04/2022

Submitted Date:

02/14/2022

Document Number:

701102660

FIELD INSPECTION FORM

Loc ID 312662 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 10 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Graves, Jim		mrinc20@maralexinc.com	
Hahn, Travis		thahn@maralexinc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222107	WELL	SI	11/01/2014	GW	077-08709	SULFUR GULCH 9-98-2 1	SI

General Comment:

COGCC Follow Up Inspection Report Summary
Follow up to 11/02/2020 inspection # 699802034
Uncorrected action items

- Tank label and placards are weathered and not legible.
- Tank by wellhead is not properly labeled.
- Well last produced October 2014. Last MIT performed on 11/13/2013 refer to document #2450053. MIT required.
- Vegetation growing on tank containment berm.

During this inspection the following compliance issues were observed:

- Road is not maintained
- No well sign.
- Weeds around location at well, production equipment and tank battery.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
Lease Road:			
Type	Access		
comment:	Road is not maintained		
Corrective Action	Maintain road.	Date:	03/16/2022
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	CONTAINERS		
Comment:	Tank by wellhead is not properly labeled.		
Corrective Action:	Containers that are used to store, treat, or otherwise handle a hazardous material are required to be marked and placarded. Properly label tank.	Date:	03/03/2020
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank label and placards are weathered and not legible.		
Corrective Action:	Operators shall maintain signs in a legible condition, and shall replace damaged signs. Replace tank label and placards.	Date:	03/03/2020
Type	WELLHEAD		
Comment:	No well sign.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/16/2022
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds around location at well, production equipment and tank battery.		
Corrective Action:	Comply with Rule 606	Date:	03/04/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	
Equipment:			
Type: Gas Meter Run	# 1		corrective date

Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	
Comment:	Weeds in berm. See housekeeping			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type		
Comment:		
Corrective Action:		
		Date:

Inspected Facilities

Facility ID: 222107 Type: WELL API Number: 077-08709 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well last produced October 2014. Last MIT performed on 11/13/2013 refer to document #2450053. MIT required.

Corrective Action: Well is overdue for Mechanical Integrity Test. Perfrom MIT on well. Date: 01/31/2020 Date: 01/31/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402955788	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5664026
701102661	Inspection 701102660 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5664024