

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/16/2022

Submitted Date:

02/23/2022

Document Number:

688312154**FIELD INSPECTION FORM**Loc ID 303187 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Foundation Energy	(866) 767-3600	regulatory@foundationenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252625	WELL	PR	02/10/1981	GW	125-06501	FONTE 1-21	PR

**General Comment:**[Routine Field Inspection](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	lease sign on CR 33		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 866-767-3600

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	2021 Form 17* is in COGCC database		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 0		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	shed (rusted), digital, 2021 calibration card is present		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Location Construction**

Location ID: 252625 CDP:

Comment:

Corrective Action:  Date:

**Form 2A COAs:**

**Comment:** No COAs.

Corrective Action:  Date:

**Wildlife BMPs:**

**Comment:**

Corrective Action:  Date:

**Comment:**

**Corrective Action:**  Date:

**On Site Inspection (305):****Surface Owner Contact Information:**

Name:  Address:

Phone Number:  Cell Phone:

**Operator Rep. Contact Information:**

Landman Name:  Phone Number:

Date Onsite Request Received:  Date of Rule 306 Consultation:

Request LGD Attendance:

**LGD Contact Information:**

Name:  Phone Number:  Agreed to Attend:

**Summary of Landowner Issues:**

**Summary of Operator Response to Landowner Issues:**

**Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**

Inspected Facilities									
Facility ID:	252625	Type:	WELL	API Number:	125-06501	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	pr 12/1/2021 production is reported to COGCC database								
Corrective Action:				Date:					

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment: [leak from GMR shed \(see attached photos\)](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688312212	Foundation Energy Fonte 1-21	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5672163">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5672163</a>