

Tecate Federal 24-22



The road near the well site has been repaired. The erosion and the side of the side of the road has been stabilized. Stormwater was diverted toward the culvert. Areas of erosion repaired and stabilized. Repairing required BMPs per Rule 1002.f.(2)C.



