

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/14/2022

Submitted Date:

02/17/2022

Document Number:

700703877

FIELD INSPECTION FORM
 Loc ID 311695 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291309	WELL	PR	01/09/2008	GW	045-14329	GENTRY C3	PR
291310	WELL	PR	07/09/2007	GW	045-14328	GENTRY C2	PR
291311	WELL	PR	01/30/2008	GW	045-14327	GENTRY C1	PR
291312	WELL	PR	12/01/2017	GW	045-14326	GENTRY C4	PR
294139	WELL	PR	12/28/2007	GW	045-15269	GENTRY C12	PR
294141	WELL	PR	05/28/2009	GW	045-15271	GENTRY C9	PR
294143	WELL	SI	09/01/2021	GW	045-15272	GENTRY C8	SI
294177	WELL	SI	08/21/2017	GW	045-15297	GENTRY C10	TA
294178	WELL	PR	05/01/2020	GW	045-15298	GENTRY C5	PR

General Comment:

COGCC Inspection Report Summary

On Monday 2/14/2022 at approximately 1000, I, Inspector Scott Ramsey, conducted a follow up inspection at TEP Gentry C, at Location # 311695 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

C/A (staining) from previous inspection # 700702749 has been completed. C/A's (debris and open cellars) Have not been completed.

Operator sent FIRR stating all C/A's have been completed, document # 402894521. C/A (stabilization) cannot be accessed due to location is snow covered.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

Location is snow covered in areas at the time of inspection and plowed.

During this inspection the following possible compliance issues were observed:

1. Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.
2. Random debris from previous inspection (C/A date 5/28/2021)
3. Open cellars and fencing from previous inspection (C/A date 5/21/2021)
4. Load line missing plug/cap.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	Snow covered/plowed		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Load line missing plug/cap.		
Corrective Action:	Install cap/bull plug	Date:	03/17/2022
Type	DEBRIS		
Comment:	Random debris from previous inspection (C/A date 5/28/2021)		
Corrective Action:	Remove all debris	Date:	05/28/2021
Type	OTHER		
Comment:	Open cellars and fencing from previous inspection (C/A date 5/21/2021)		
Corrective Action:	Eliminate possibility of wildlife/personal to enter open cellars	Date:	05/21/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:	Fencing is open in areas		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 9		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	HEATED STEEL AST		,

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 291309	Type: WELL	API Number: 045-14329	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 291310	Type: WELL	API Number: 045-14328	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 291311	Type: WELL	API Number: 045-14327	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 291312	Type: WELL	API Number: 045-14326	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 294139	Type: WELL	API Number: 045-15269	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 294141	Type: WELL	API Number: 045-15271	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:				Date:
Facility ID: 294143	Type: WELL	API Number: 045-15272	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: Last produced 8/2021				
Corrective Action:				Date: _____
Facility ID: 294177	Type: WELL	API Number: 045-15297	Status: SI	Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: [Last MIT done 1/24/2018](#)

Corrective Action: _____

Date: _____

Facility ID: 294178 Type: WELL API Number: 045-15298 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing](#)

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Limited storm water inspection due to snow cover](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402959527	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5667893
700703887	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5667883