

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/17/2022

Submitted Date:

02/18/2022

Document Number:

693700924**FIELD INSPECTION FORM**
 Loc ID 472211 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
General, All inspections	(970) 332-3520	cogccinspection@pdce.com	All PDC inspection

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481494	SPILL OR RELEASE	CL			-	Noffsinger 11-33	EI

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type			
Comment:	Operator has conducted excavation exposed to groundwater adjacent to public road. Operator personnel were present onsite working excavation. No evidence of plans to fence excavation were observed.		
Corrective Action:	Install adequate fencing or barrier or other protective measures to prevent risk to public travelling on County Road when excavation is not attended.		Date: <u>02/18/2022</u>

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spill/Remediation:**

Comment: Operator has conducted excavation and exposed groundwater at Noffsinger 11,31-33 tank battery. Excavation is apparently being conducted in response to reported Release 481494 on the flowline from the Noffsinger 11-33. Operator has approved Remediation Project for Noffsinger 11-33 well investigation and flowline removal.

No Form 27 Site Investigation and Remediation Workplan was submitted for removal of the remaining production equipment pursuant to Rule 911.a. and the Condition of Approval issues on Form 19 Document #402942390: "Please submit a Form 27 Initial for the removal of the produced water vessel or production equipment not associated with the flowline release."

Corrective Action: Operator shall submit Form 27 for remediation of release at tank battery. Operator shall include data to make a determination whether impacts are a result of single release at flowline or multiple sources at tank battery were discovered. Operator is currently out of compliance with Rule 911.a.

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402960129	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5668428
693700925	Noffsinger11,31-33Photos_2-17-2022	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5668426