

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/25/2022

Submitted Date:

02/28/2022

Document Number:

696303984

**FIELD INSPECTION FORM**

Loc ID 424875 Inspector Name: PETRIE, ERICA On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10503  
Name of Operator: RED HAWK PETROLEUM LLC  
Address: 575 N DAIRY ASHFORD STE 201  
City: HOUSTON State: TX Zip: 77079

**Findings:**

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Shepard, DeAnn		dshepard@pedevco.com	<a href="#">All Inspections</a>
Kraich, Adam		adam.kraich@state.co.us	
Boyd, William		wboyd@pedevco.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424885	WELL	PR	08/01/2021	OW	123-34205	Perrin 1-10H	PR

**General Comment:**

This is a Follow-Up Inspection to FIR 6963039960 dated 02.11.2022 is Response to Gas Meter Valves being closed and ECD Pilot Light not ignited.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Produced Water Tank NFPA Label and Middle Crude Oil Tank Content and Capacity Labels are Fading - Consider Replacing Soon.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Valves on Gas Meter going to ECD are now open. Sales Line STILL Locked Out/Tagged by Gathering Company		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		

Comment:	Pilot Light now ignited	Date:	
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:		Date:	
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	FIBERGLASS AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with the Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	400 BBLs	STEEL AST		40.594930,-104.299620
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:	Gas Produced from Well going to ECD NOT Sales. Sales Meter is Locked Out/Tagged Out. Gas being vented or flared during non-upset condition without prior approval from COGCC.	
Corrective Action:	Immediately cease venting/flaring. Comply with Rule 903.d.	Date: 02/12/2022

<b>Flaring:</b>			
Type	Ignitor/Combustor		
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 424885 Type: WELL API Number: 123-34205 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit						
<b>Storm Water:</b>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input style="width:90%;" type="text"/> Corrective Action: <input style="width:90%;" type="text"/>						Date: _____
<b>Pits:</b> <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments		
Comment	User	Date
<p>COGCC Inspection Report Summary                      On Thursday 02/25/2022 approximately 15:13, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at Red Hawk Petroleum LLC, Perrin 1-10H at Location #424875 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Well actively Producing. Sales Line was Locked Out/Tagged Out; all Valves on Sales are Closed. Valves to the ECD are Open. Gas can either go to Sales or ECD. Gas Produced is currently being Flared off through ECD. No Approved Form 4 on File pursuant to Rule 903.d</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	petrie	02/25/2022

**Attached Documents**

You can go to COGCC Images (<https://ogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696303985	Pumping Unit Running	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5675939">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5675939</a>
696303986	FLIR of ECD	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5675940">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5675940</a>
696303987	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5675941">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5675941</a>