

Complaint 402966233

COGCC database flowline locations (approximate) and flowline marker signs as observed 25Feb2022

area where hydrocarbon impacted soils observed by crew potholing utilities (in contact with groundwater)

Facility 4 East Consolidation 1 KPK as shown in COGIS

Manifold 479311

KPK line marker

KPK line marker

HS Resources sign

removed line 10517329-02 Oxy as shown in COGIS

UPRR 42-PAN-AM-AE 2

