

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC EXXON-66S95W /32SESE

Location ID: 323885



Photo #6053 from entrance to location.



Photo #6054 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC EXXON-66S95W /32SESE

Location ID: 323885



Photo #5881 from Inspection #699804117 conducted on 2/7/22.



Photo #6055 Insufficient tracking control at entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC EXXON-66S95W /32SESE

Location ID: 323885



Photo #5882 from Inspection #699804117 conducted on 2/7/22.