

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2022

Submitted Date:

02/28/2022

Document Number:

699804204**FIELD INSPECTION FORM**Loc ID 334733 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290040	WELL	PR	08/01/2021	GW	045-13964	MAP LLC 11-11(PK11)	PR
290042	WELL	SI	07/01/2021	GW	045-13962	MAP LLC 11-13 (PK11)	SI
290043	WELL	PR	04/19/2008	GW	045-13961	MAP LLC 11-14 (PK11)	PR
292399	WELL	PR	04/20/2008	GW	045-14721	MAP LLC 11-11BB (PK11)	PR
292400	WELL	SI	07/01/2021	GW	045-14720	MAP LLC 11-13BB (PK11)	SI
292488	WELL	PR	08/01/2021	GW	045-14729	MAP LLC 11-12BB (PK11)	PR
293124	WELL	PR	10/25/2007	GW	045-14899	MAP LLC 11-14BB (PK11)	PR

General Comment:**COGCC Inspection Report Summary**

On Friday 2/25/22 at approximately 12:30 hours, I, Inspector Corey De Paolo,
Conducted an on-site inspection at CAERUS PICEANCE LLC MAP LLC-67S95W /11NESW,
Location #334733 in Garfield County Colorado.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1) No battery sign located at the tank battery with a corrective action date of 4/25/22.

A follow up on this site inspection needs to be conducted to ensure the
Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	No battery sign located at the tank battery.		
Corrective Action:	A permanent, conspicuous sign will be located at the tank battery.	Date:	04/25/2022
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Vertical Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 7		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit midstream		
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:	Pressure transducers located on braden head. All braden head valves are accessible.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type			
Comment:			
Corrective Action:			
		Date:	

Inspected Facilities				
Facility ID: 290040	Type: WELL	API Number: 045-13964	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:			Date:	
Facility ID: 290042	Type: WELL	API Number: 045-13962	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: Last produced June 2021				
Corrective Action:			Date:	
Facility ID: 290043	Type: WELL	API Number: 045-13961	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:			Date:	
Facility ID: 292399	Type: WELL	API Number: 045-14721	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:			Date:	
Facility ID: 292400	Type: WELL	API Number: 045-14720	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: Last produced June 2021				
Corrective Action:			Date:	
Facility ID: 292488	Type: WELL	API Number: 045-14729	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:			Date:	
Facility ID: 293124	Type: WELL	API Number: 045-14899	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing				
Corrective Action:			Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
		Culverts				
		Ditches				
Berms						
Other						
Ditches						
		Sediment Traps				
Sediment Traps						
		Berms				
		Gravel				

Comment: [Limited storm water inspection due to location being covered with snow.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Refer to Signs/Markers for corrective actions	depaoloc	02/28/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699804205	Photos for Insp. #699804204	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5679430